

Date: 07/20/2007

Recall Notice

Sierra International is issuing an **Immediate Recall** on the Fuel Connectors and Fuel Line Assemblies listed below. These products are not manufactured to Sierra's material specifications and **CAN NOT** be field repaired and must be returned to Sierra International. The materials used to manufacture these connectors may break down over time and create a potential for fuel leakage. Every attempt should be made to remove the following date coded product from all distributor and dealer inventories.

Following product and date codes are affected:

207 -

	P/N	Beginning Date Code	Ending Date Code	P/N	Beginning Date Code	Ending Date Code
-0036	18-8009	070105	070107	18-8031	070106	071107
	18-8014	070105	070107	18-8036	070106	071107
	18-8016	070106	071107	18-8056	071505	070107
	18-8022	070106	071107	18-8056-10	070106	070107
	18-8024	070106	071107	18-8059	070105	070107
	18-8025	071506	071107	18-8066	070106	070107
	18-8029	070106	071107	18-8085	070106	071107



Date codes are read as Year, Day, Month. (ex 070106 manufactured 2007, 01, June)

Our records indicate that you have recently received a select quantity of one or multiples of the above mentioned products, please contact our Technical Service Dept. at 217-324-9400 to obtain a Return Goods Authorization number. An offsetting credit will be issued for the recalled products upon receipt. Replacement inventory will be available for shipment July 24, 2007. Please contact our Customer Service Dept. at 217-324-9400 to reorder.

We apologize for the inconvenience incurred due to this recall. If you have further questions or concerns, please contact our Technical Service Dept. at 217-324-9400

Sincerely

Larry Louvier
Product Manager - Sierra International

Sierra International, 1 Sierra Place, Litchfield, IL 62056 Phone: 217-324-9400 Fax: 217-324-2461
www.teleflexmarine.com